
DCL-PAR117



For a more transparent finish on the cover, paint it with glossy varnish.




3D resin is fragile, so you should NOT use excessive force when joining the pieces or you risk breaking the parts.


Carry out a test assembly before painting the parts, sanding where necessary and preferably the plastic parts of the kit, until the parts fit together with light pressure without being forced.





gondabox.com 3D design

DCL-PAR117 Parts size











gondabox.com 3D design